

For Pre-Processing For Plating


Do you have trouble with gas-generation after molding?  
 You can use this low-priced anneal oven!

## Box-Type Dryer (Anneal Oven)

6

**Overview** PO is box-type dryer and batch-type with 10-30 trays.  
 Setting temperature is kept by rational design and PID control  
 in relation to circulating hot air.

Defectiveness with the out gas after  
 the plating processing



[ PO-120 ]

- Features**
- Container and trays can be removed (according to molded part size).
  - Easy to set and change temperatures.
  - Start time can be set by start-up timer use.
  - Breaker used with shunt coil at peak time, the power shuts off for safety.
  - Standard equipment includes overheat protector (Liquid expansion-type). This will shut the unit down at the pre-determined temperature.
  - Protects equipment by shutting down power if heater is abnormal by breaker points fused detector.
  - Long life sheathed heater is used.

