

## 2 Eliminate wasted resin

**Resource  
consumption cut**

Productivity UP

Added Value UP

**Ideal for Molding High-mix Small-lots**



Are you wasting a lot of material when changing colors just to prevent color irregularities?  
Change colors quickly and efficiently, and with uniform mixing!

### Static Mixer

#### Overview

Completes color changes in 3 to 4 shots through smooth material changeover.  
Simply mount the mixer to the tip of the mold machine nozzle to achieve uniform distribution of additives and uniform temperature distribution during mixing.



#### Features

- Requires no power, takes no space.
- Uniform distribution of materials and temperature.
- Only 3 to 4 wasted shots when changing materials.
- ROI is around several weeks.

