

4 Shorten set up times

Resource
consumption cut

Productivity UP

To Achieve Quicker Material Changeover

Added Value UP

Whenever switching materials, do you wasting time and materials to avoid mixing unevenness?
Get uniform mixing and quick and efficient color changes!



Static Mixer

Overview

Completes color changes in 3 to 4 shots through smooth material changeover. Simply mount the mixer to the tip of the mold machine nozzle to achieve uniform distribution of additives and uniform temperature distribution during mixing.



Features

- Requires no power, takes no space.
- Uniform distribution of materials and temperature.
- Only 3 to 4 wasted shots when changing materials.
- ROI is around several weeks.

