

8 Resolve problems caused by gas

Resource
consumption cut

Productivity UP

For Pre-Processing For Plating

Added Value UP


Do you have trouble with gas-generation after molding?
You can use this as a low-priced anneal oven.

Box-Type Dryer (Anneal Oven)

Overview

PO is box-type dryer and batch-type with 10-30 trays.
Setting temperature is kept by rational design and PID control in relation to circulating hot air.

Defectiveness with the out gas after
the plating processing



[PO-120]

Features

- Container and trays can be removed (according to molded part size).
- Easy to set and change temperatures.
- Start time can be set by start-up timer use.
- Breaker used with shunt coil at peak time, the power shuts off for safety.
- Standard equipment includes overheat protector (Liquid expansion-type).
This will shut the unit down at the pre-determined temperature.
- Protects equipment by shutting down power if heater is abnormal by breaker points fused detector.
- Long life sheathed heater is used.

[illegible]