

10 Improve dimensional precision

**For Stress Deduction Of
Molded Products**

Resource
consumption cut

Productivity UP

Added Value UP

Want to reduce residual stress after molding?
Use as a low-priced anneal oven.

Box-Type Dryer (Anneal oven)

Overview

PO is box-type dryer and batch-type with 10-30 trays.
Setting temperature is kept by rational design and PID control in relation to circulating hot air.



[PO-120]

Features

- Container and trays can be removed (It is possible to use according to molded part size).
- Easy to set and change temperatures.
- Start time can be set by start-up timer use.
- Breaker used with shunt coil at peak time, the power shuts off for safety.
- Standard equipment includes overheat protector (Liquid expansion-type). This will shut the unit down at the pre-determined temperature.
- Protects equipment by shutting down power if heater is abnormal by breaker points fused detector.
- Long life sheathed heater is used.

