

## 8 Resolve problems caused by gas

Resource  
consumption cut

**Productivity UP**

**For Resin Containing lots of gas**

Added Value UP

Do you see white deposits on the ceiling of the molding room?  
They can cause contamination!  
Solidify and collect resin gas that generate these white deposits,  
preventing them from scattering!

### Indirect Cooling Type Gas Collection System

#### Overview

Attached to the exhaust line of the dryer, this unit solidifies through indirect cooling and collects the gas composition volatilized from the resin materials.\*



[Gas Removal]



Setup image

Gas removed

#### Features

- No complicated wiring is required. Just mount the unit and plug it in!
- Compact design for less space usage.
- Can be attached to both ventilation type and dehumidifier type dryers.

\* Not all volatilized compositions can be collected.

